

ANNUAL SURVEYS.

40686

No. 488 Survey held at London Date, first Survey 13 July Last Survey 14 July 18 87
 No. in on the S.S. Celtic Monarch Master Wilson
 Reg. Book. 488 Net 1308 Built at Newcastle When built 1879 Month. 2
 Tonnage Gross 2014 Under Dk. 1154 By whom built Richardson Owners Royal L. Co.
 Port belonging to London Destined Voyage America
 If Surveyed Afloat or in Dry Dock Paplar dry dock
 (State Name of Dock.)

Last Survey, No. 40050 Port of London Classed 100 A1 Years assigned. 1.81 Character in Register Book.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Reset</u>	Roofs	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Windlass and Capstan	<u>Good</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Pumps	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Boats	<u>four</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Condition, how ascertained	<u>from deck</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Sails	<u>well found</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Anchors, No. of	<u>3 B. 1 S. & Wedges</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Cables	<u>complete</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M.	When put on	Hawsers and Warps	<u>sufficient</u>
Engine Room Skylights	<u>do</u>	Caulking of		Standing and Running Rigging	<u>good</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Bottom, Deck, & Waterways	<u>do</u>	Cargo and Main Hatchways	<u>do</u>
Scuppers	<u>do</u>			Hatches	<u>do</u>

General Observations, Opinion as to Class, &c.
Bottom recoated where required. Rudder and
steering gear made good and other smaller repairs & to fittings
This vessel appears eligible to remain as classed

Committee's Minute Tuesday, August, 9th 1881. Geo. Longdon
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
U.B. Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the	Decks	Treenails	Breasthooks and Stemson	Windlass and Capstan
Waterways	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Comings	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Upper Deck Beams & Fastenings	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Lower Deck Beams & Fastenings	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Planksheers	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Sheerstrakes	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Topsides	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Wales	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Plank (Bottom) and Counter	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Engine Room Skylights	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Coal Bunkers, Openings, Lids, &c.	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Scuppers	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Cargo and Main Hatchways	<u> </u>	<u> </u>	<u> </u>	<u> </u>
Hatches	<u> </u>	<u> </u>	<u> </u>	<u> </u>

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Celtic Monarchs



© 2021

Lloyd's Register
Foundation