

# ANNUAL SURVEYS.

40695

(Received at London Office) Friday, August, 5th, 1881

No. 568 Survey held at London Date, first Survey 30 July Last Survey 3 August 18 81  
 No. in Reg. Book on the S.S. Charles Gapper Master Walton  
 Tonnage { Net 479 Built at Newcastle When built 1864  
 { Gross 761 By whom built Palmer Bros. Owners Dixon & Harris  
 { Under Dk. 706 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock London dry dock

Last Survey, No. 40124 Port of Lon.

Classed 85 A1  
 Character in Register Book. S.S. 402.79 - 2.81.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>Three</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Condition, how ascertained	<u>from deck</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Sails	<u>well found</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Anchors, No. of	<u>3 B.I.S. &amp; Hedges</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>complete</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>sufficient</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. When put on	<u>do</u>	Standing and Running Rigging	<u>good</u>
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	Cargo and Main Hatchways	<u>do</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>do</u>	Hatches	<u>do</u>

General Observations, Opinion as to Class, &c. Bottom recoated and rudder pintles hatched.  
This vessel appears eligible to remain as classed.

Committee's Minute Friday, August, 12th 1881.  
 Character assigned 85 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Longdon  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_  
 No. in Reg. Book on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 { Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 { Under Dk. \_\_\_\_\_ Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Coal Bunkers, Openings, Lids, &c.	Scuppers	Hatches

General Observations, Opinion as to Class, &c. \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_ 18 \_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) Paid 18



Chas. Cepper



© 2021

Lloyd's Register  
Foundation