

ANNUAL SURVEYS.

No. 1064 Survey held at London Date, first Survey Aug 8 Last Survey Aug 10th 1881
 No. in on the SS Minerva Master Wright
 Reg. Book. 1064 Tonnage { Net 427 Built at Newcastle When built 1862
 Gross 676 By whom built Palmer Owners Sen Shm Ship Co
 Under Dk. 605 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St (State Name of Dock.)

Last Survey, No. 27256 Port of Iron

Classed 95A 7.80
 Years assigned. SS Lin M. 1.75
 Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Brushed
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated. She is now in an efficient state and eligible to remain as Clasp

Committee's Minute Friday, August, 20th 1881

Character assigned 95A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 1064 Survey held at London Date, first Survey Aug 8 Last Survey Aug 10th 1881

No. in on the SS Minerva Master Wright
 Reg. Book. 1064 Tonnage { Net 427 Built at Newcastle When built 1862
 Gross 676 By whom built Palmer Owners Sen Shm Ship Co
 Under Dk. 605 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St (State Name of Dock.)


Last Survey, No. 27256 Port of Iron

Classed 95A 7.80
 Years assigned. SS Lin M. 1.75
 Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Brushed
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated. She is now in an efficient state and eligible to remain as Clasp

Committee's Minute 18

Character assigned 95A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

LONG666-0414