

ANNUAL SURVEYS.

No. 4042 Survey held at Londonderry Date, first Survey Aug 12 Last Survey Aug 18 1881
 No. in on the SS Viking Master R. J. J. J.
 Reg. Book. 237 Net 1686 Built at Glasgow When built 1874 Year. 6 Month. 6
 Tonnage Gross 2588 Under Dk. 1753 By whom built Witten Owners N. Poppe
 Port belonging to Glasgow Destined Voyage Newport & Montreal
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock (State Name of Dock.)

Last Survey, No. 40203 Port of Lon
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. owing to damage 3 Propeller blades renewed

She is now in an efficient state and eligible to remain as classed
Senhouse Martinide

Committee's Minute Tuesday August, 30th 1881.
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
B & M P. 2, 77 subject to Certificate (if required, to be sent as per margin) Paid 18

No. 4042 Survey held at Londonderry Date, first Survey Aug 12 Last Survey Aug 18 1881
 No. in on the SS Viking Master R. J. J. J.
 Reg. Book. 237 Net 1686 Built at Glasgow When built 1874 Year. 6 Month. 6
 Tonnage Gross 2588 Under Dk. 1753 By whom built Witten Owners N. Poppe
 Port belonging to Glasgow Destined Voyage Newport & Montreal
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock (State Name of Dock.)

Last Survey, No. 40203 Port of Lon Classed 100A
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. owing to damage 3 Propeller blades renewed

Committee's Minute 18
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LONG666-0430

My



© 2021

Lloyd's Register
Foundation