

ANNUAL SURVEYS.

No. 40750 Survey held at London Date, first Survey July 28th Last Survey Aug 2nd 1881

No. in on the SS Aurora Master J. Bodder
 Reg. Book. 1423 Net 446 Built at Newcastle When built 1863 Year. 6 Month.
 Tonnage Gross 411 Under Dk. 646 By whom built Palmer Owners London & N. Ship Co
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock (State Name of Dock.)

Last Survey, No. 27563 Port of Lron Classed 25A-7.80
 Years assigned. SS. Lm M 2.80 Character in Register Book. SS. No 3. 72.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 General Observations, Opinion as to Class, &c. Bottom be coated.

She is now in an efficient state and eligible to remain as classed

Senhouse Martindale

Committee's Minute Friday, September, 2nd 1881.

Character assigned B. S. 87 81

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

14710-0044



© 2021

Lloyd's Register
Foundation