

ANNUAL SURVEYS.

40759

No. 40759 Survey held at Deptford Date, first Survey 23rd Aug Last Survey 24th Aug 1881
 No. in on the Iron S. "Fogley" Master D. Napier
 Reg. Book. 445 Net 1598 Built at Swanland When built 1874 9
 Tonnage Gross 1664 Under Dk. 1579 By whom built Oswald Owners J. Hourse
 Port belonging to London Destined Voyage Rio de Janeiro
 If Surveyed Afloat or in Dry Dock Walker's dry dock
 (State Name of Dock.)

Last Survey, No. 27500 Port of Iron
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways — Breasthooks and Stenson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shells —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. Cement When put on 1874
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.
Bottom repainted. She is now in good condition and in our opinion eligible to continue as Classed

Committee's Minute Friday, September, 2nd 1881.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. — Survey held at Deptford Date, first Survey 23rd Aug Last Survey 24th Aug 1881
 No. in on the Iron S. "Ogloey" Master H. Evans
 Reg. Book. 93 Net 1381 Built at Swanland When built 1880 6
 Tonnage Gross 1438 Under Dk. 1286 By whom built R. Foster Owners Arvon Ship Co Ltd
 Port belonging to Liverpool Destined Voyage San Francisco via Calif
 If Surveyed Afloat or in Dry Dock Walker's dry dock
 (State Name of Dock.)

Last Survey, No. 27315 Port of Iron
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways — Breasthooks and Stenson —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shells —
 Topsides — Ceiling —
 Wales — Rudder —
 Plank (Bottom) and Counter — Copper or Y.M. Cement When put on 1880
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom repainted. She is now in good condition and in our opinion eligible to continue as Classed
 Committee's Minute Friday, September, 2nd 1881.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON666-0454