

ANNUAL SURVEYS.

No. 40760 Survey held at London Date, first Survey Aug 4th Last Survey Aug 24th 1881
 No. in on the 18th Lile Master _____
 Reg. Book. 418 Net 245 Built at Plymouth When built 1844 Year. _____ Month. _____
 Tonnage { Gross 245 By whom built _____ Owners J. B. Ellis
 Under Dk. 237 Port belonging to Plymouth Destined Voyage not known
 If Surveyed Afloat or in Dry Dock at Wharf in the mud. (State Name of Dock.)

Last Survey, No. 39623 Port of London Classed 12 A Character in Register Book. Ren. L. 74-8 sub 2-77
 Present Condition of the
 Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. When put on 7/2/80
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "

General Observations, Opinion as to Class, &c. This vessel Main Deck has been doubled with Yellow Pine in Liverpool but it appears the surveyors were not informed of it. She is in an efficient state respectfully recommend her to be classed and entered in the Register Book as recommended by Mr. Davey in his Report attached (which only arrived from Liverpool this day 3/8/81) Best At 8 & marks HT 80
 Committee's Minute Friday, September, 2nd 18 81. Senhouse Macdonald
 Character assigned Res P A Surveyor to Lloyd's Register of British and Foreign Shipping.

D. d. 81 Sept. 20 Certificate (if required, to be sent as per margin) Paid 18

No. 40760 Survey held at London Date, first Survey _____ Last Survey _____ 1881
 No. in on the _____ Master _____
 Reg. Book. _____ Net _____ Built at _____ When built _____ Year. _____ Month. _____
 Tonnage { Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the
 Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid _____ 18 _____