

ANNUAL SURVEYS.

* 40.767

No. Survey held at London Date, first Survey Aug 4th Last Survey Aug 23rd 1881
(Received at London Office, 3/9/81)
 No. in on the SS Taymouth Castle Master J. Mullon
 Reg. Book. 96 Net 1172 Built at Glasgow When built 1877 3
 Tonnage Gross 1827 Under Dk. 1790 By whom built Bailey & Co Owners J. Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock James J. W. & Co. Dry Dock
(State Name of Dock.)

Last Survey, No. 40060 Port of Lon Classed 100A 281
Years assigned. Character in Register Book.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches Windlass and Capstan Good
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings Pumps
 Lower Deck Beams & Fastenings Ditto ditto at other places Boats
 Planksheers Keelsons Masts, Yards, &c.
 Sheerstrakes Clamps and Shelves Condition, how ascertained From St
 Topsides Ceiling Sails
 Wales Rudder Anchors, No. of 3 Nos. St & High
 Plank (Bottom) and Counter Copper or Y.M. Scanted When put on Nov Cables Par on St
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
(If Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. Bottom & counter, She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18


Committee's Minute 18
 Character assigned SP 100A

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Year. Month.
 Tonnage Net Built at When built
Gross By whom built Owners
Under Dk.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches Windlass and Capstan
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings Pumps
 Lower Deck Beams & Fastenings Ditto ditto at other places Boats
 Planksheers Keelsons Masts, Yards, &c.
 Sheerstrakes Clamps and Shelves Condition, how ascertained
 Topsides Ceiling Sails
 Wales Rudder Anchors, No. of
 Plank (Bottom) and Counter Copper or Y.M. When put on Cables
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Committee's Minute 18
 Character assigned



(Form No. 5 for A.L. 1.1. 1913 when here are no
 The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

Year	Part of	Last Survey, No.	Present Condition of the
1870
1871
1872
1873
1874
1875
1876
1877
1878
1879
1880
1881
1882
1883
1884
1885
1886
1887
1888
1889
1890
1891
1892
1893
1894
1895
1896
1897
1898
1899
1900

Committee's Minutes
 Character assigned

Year	Part of	Last Survey, No.	Present Condition of the
1870
1871
1872
1873
1874
1875
1876
1877
1878
1879
1880
1881
1882
1883
1884
1885
1886
1887
1888
1889
1890
1891
1892
1893
1894
1895
1896
1897
1898
1899
1900

