

ANNUAL SURVEYS.

40489

No. 488 Survey held at London Date, first Survey 1st Sept^r Last Survey 2nd Sept^r 1887
 N. in on the “ Celtic Monarch ” Master Wilson
 reg. Book 488 Net 1308 Built at Newcastle When built 1879 Year. 18 Month. 9
 Tonnage Gross 2014 Under Dk. 1854 By whom built W. Richardson Owners Royal Exchange St^d Co. Ltd.
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Popular dry Dock
 (State Name of Dock.)

Last Survey, No. 40686 Port of Lon Classed 100 A 1
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shells Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 1879
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom repainted. She is now in good condition and eligible in an opinion to continue as Classed

Committee's Minute Friday, September, 16th 1881.
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 3/ Paid 20/9/21/81

No. 488 Survey held at London Date, first Survey 1st Sept^r Last Survey 2nd Sept^r 1887
 No. in on the “ Celtic Monarch ” Master Wilson
 reg. Book 488 Net 1308 Built at Newcastle When built 1879 Year. 18 Month. 9
 Tonnage Gross 2014 Under Dk. 1854 By whom built W. Richardson Owners Royal Exchange St^d Co. Ltd.
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Popular dry Dock
 (State Name of Dock.)

Last Survey, No. 40686 Port of Lon Classed 100 A 1
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shells Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 1879
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom repainted. She is now in good condition and eligible in an opinion to continue as Classed

Committee's Minute 18
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 3/ Paid 20/9/21/81