

ANNUAL SURVEYS.

40809


No. 433 Survey held at London Date, first Survey Augst 26 Last Survey Augst 26 1881
 (Received at London Office, 3/9/81)
 No. in Reg. Book 433 on the S. S. Glenavon Master A. Taylor
 Tonnage { Net 1936 Built at Glasgow When built 1881 Month 2
 Gross 2985
 Under Dk. 2696 By whom built Lon. & Glas. Co. Owners M' Gregor, Gow & Co.
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Poplar dry dock
 (State Name of Dock.)

Last Survey, No. 5342 Port of Gls. Classed 100 A 1
 Years assigned 4-81 Character in Register Book
 Present Condition of the Decks Good ~~Treenails~~ Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Rudder "
 Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From deck
 Sails Good
 Anchors, No. of 3 B^{ns} / Stream, 2 Ridges
 Cables Part seen on 18th Good
 Hawfers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom painted. This vessel is now in good condition, and eligible in my opinion to remain as classed.

Committee's Minute Tuesday, September, 20th 18 81. Charles Edwards
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book _____ on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____
 Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)
 Last Survey, No. _____ Port of _____ Classed _____
 Years assigned _____ Character in Register Book _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Rudder _____
 Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawfers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18____



LON 666-0526