

ANNUAL SURVEYS.

40870

No. 95 Survey held at London Date, first Survey Aug 13 Last Survey Sept 10th 1881
 No. in on the SS Warwick Castle Master A Manchester
 Reg. Book. 95 Tonnage { Net 1892 Built at Glasgow When built 1877 Year. 8 Month. 8
 Gross 2957 By whom built Napier Owners J Currie & Co
 Under Dk. 2869 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens Dry Dock & afloat
(State Name of Dock.)

Last Survey, No. 40452 Port of London Classed 100A-5.81
Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"	
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.	"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Condition, how ascertained	<u>From SK</u>	
Planksheers	"	Keelsons	"	"	Sails	<u>Good</u>	
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors, No. of <u>3 Bes. SK & Redys</u>	"	
Topsides	"	Ceiling	"	"	Cables <u>Part in SK</u>	<u>Good</u>	
Wales	"	Rudder	"	"	Hawsers and Warps	"	
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Covered</u>	When put on <u>Nov</u>	"	Standing and Running Rigging	"	
Engine Room Skylights <u>Good</u>	Coal Bunkers, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches	"

General Observations, Opinion as to Class, &c. Bottom is covered. She is now in an efficient state and eligible to remain as classed

Senhouse Martindale


Committee's Minute Tuesday, September, 20th 1881.
 Character assigned 100A-5.81 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage { Net _____ Built at _____ When built _____ Year. _____ Month. _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. _____	Standing and Running Rigging
Engine Room Skylights _____	When put on _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Caulking of Bottom, Deck, & Waterways _____	Hatches _____
Scuppers _____	General Observations, Opinion as to Class, &c. _____	

Committee's Minute 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LON666-0528

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

ANNUAL SURVEYS

Harriet Butler



© 2021

Lloyd's Register
Foundation