

ANNUAL SURVEYS.

40815

No. 1267 Survey held at London Date, first Survey Sept 2^d Last Survey Sept 14th 1881
 No. in Reg. Book. 1267 on the BK Mountain Laurel Master N. Gore
 Tonnage 620 Built at Harrington When built 1865. 2.
 By whom built R Williamson & Son Owners J Thompson
 Port belonging to Liverpool Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens St & afloat

Last Survey, No. 28799 Port of Iron
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated.
She is now in an efficient state and eligible to remain as classed.

Years assigned. 10.80
 Character in Register Book.
 Classed AA1
SS Liv No 3.78.

Committee's Minute Friday, September, 23^d 1881.
 Character assigned Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1881

No. 324 Survey held at London Date, first Survey Aug 25 Last Survey Sept 2^d 1881
 No. in Reg. Book. 324 on the BK Ironhoe Master J Houston
 Tonnage 1383 Built at Glasgow When built 1868. 10
 By whom built J Reid & Co Owners J & G Wittingham
 Port belonging to Melbourn Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Canal by St & afloat

Last Survey, No. 28283 Port of Iron
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated.
She is now in an efficient state and eligible to remain as classed.

Years assigned. 11.80
 Character in Register Book.
 Classed AA1
SS Mel No 3.80.

Committee's Minute Friday, September, 23^d 1881.
 Character assigned Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1881

Lloyd's Register
Foundation