

# ANNUAL SURVEYS.

40815

Tuesday, September, 20th 81.

No. 1267 Survey held at London Date, first Survey Sept 27 Last Survey Sept 14 1881  
 No. in on the BK Mountain Laurel Master N Gore  
 Reg. Book. 1267 Tonnage 620 Built at Harrington When built 1865. 2.  
 By whom built R Williamson & Son Owners J Thompson  
 Port belonging to Liverpool Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Greens St & afloat

Last Survey, No. 28799 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom &c coated.  
She is now in an efficient state and eligible to remain as classed.

Years assigned. 10.80  
 Character in Register Book.  
 Classed AA1 SS Liv No 3.78.

Committee's Minute Friday, September, 23rd 1881.  
 Character assigned Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 1881

No. 324 Survey held at London Date, first Survey Aug 25 Last Survey Sept 2 1881  
 No. in on the BK Ironhoe Master J Houston  
 Reg. Book. 324 Tonnage 1383 Built at Glasgow When built 1868. 10  
 By whom built J Reid & Co Owners J & G Wittingham  
 Port belonging to Melbourne Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Canal by St & afloat

Last Survey, No. 28283 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom &c coated.  
She is now in an efficient state and eligible to remain as classed.

Years assigned. 11.80  
 Character in Register Book.  
 Classed AA1 SS Mel No 3.80.

Committee's Minute Friday, September, 23rd 1881.  
 Character assigned Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 1881



Lloyd's Register  
Foundation