

# ANNUAL SURVEYS.

40830

No. 991 Survey held at London Date, first Survey 13 Sept Last Survey 16 Sept 18 81  
 No. in on the P. P. Clement Master Hill  
 Reg. Book. 991 Net 974 Built at Stockton When built 1879 Year. 6 Month. 6  
 Tonnage Gross 1529 Under Dk. 1384 By whom built Pearse & Owners bloate &  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock Linethil dry dock (State Name of Dock.)

Last Survey, No. 3150 Port of London Npt. Classed 100 A. Years assigned. 4.80 Character in Register Book.  
 Present Condition of the Decks Good Treenails Reinforced Easels Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓  
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do  
 (If a Steam Ship, state if a Report is also sent on the Machinery .....)  
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated. This vessel appears eligible to remain as classed

Committee's Minute Friday, September, 30th 1881. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Character assigned 100 A. Certificate (if required, to be sent as per margin) Paid 18

No.        Survey held at        Date, first Survey        Last Survey        18         
 No. in on the        Master         
 Reg. Book.        Net        Built at        When built        Year.        Month.         
 Tonnage Gross        Under Dk.        By whom built        Owners         
 Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock        (State Name of Dock.)

Last Survey, No.        Port of        Classed        Years assigned.        Character in Register Book.  
 Present Condition of the Decks        Treenails         
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M.        When put on         
 Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
 (If a Steam Ship, state if a Report is also sent on the Machinery .....)  
 Observations, Opinion as to Class, &c.       

Committee's Minute 18  
 Character assigned

Clyment



© 2021

Lloyd's Register  
Foundation