

ANNUAL SURVEYS.

40843
Recd 1. 10. 81

No. in Reg. Book. **No.** 1653 Survey held at London Date, first Survey Sept 26th Last Survey Sept 28th 18 81,
on the SS Bothwell Castle Master _____
Tonnage 2542 Built at Middlesbrough When built 1881 - 3
By whom built R Dixon & Co Owners J Skinner & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Thames & N Dock

Last Survey, No. 4614 Port of London Classed 100A. 4. 81
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom & coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, October, 4th 1881.
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) DBW Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
No. in Reg. Book. on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Present Condition of the
Decks _____ Treenails _____
Waterways _____ Breasthooks and Stemson _____
Comings _____ Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
Planksheers _____ Keelsons _____
Sheerstrakes _____ Clamps and Shelves _____
Topsides _____ Ceiling _____
Wales _____ Rudder _____
Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____