

12/10/81

ANNUAL SURVEYS.

40894

No. 5 Survey held at London Date, first Survey Sept 19th Last Survey Oct 12th 1881
No. in on the S Loch Eck Master P Taylor
Reg. Book. 575 Net 1641 Built at Glasgow When built 1874 Year. Month.
Tonnage Gross 1701 By whom built C. Bennett & Co Owners J & R Wilson
Under Dk. 1548 Port belonging to Glasgow Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Pontoon Victoria St & afloat
(State Name of Dock.)

Last Survey, No. 28537 Port of Iron
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stenson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c. Bottom & coated
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday, October, 14th 1881.
Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 494 Survey held at London Date, first Survey Sept 12th Last Survey Oct 12th 1881
No. in on the S Roman Empire Master J Adams
Reg. Book. 494 Net 1542 Built at W Heathcote When built 1866 Year. Month.
Tonnage Gross 1542 By whom built Pile Owners G Duncan
Under Dk. 1467 Port belonging to London Destined Voyage Auckland
If Surveyed Afloat or in Dry Dock Pontoon Victoria St & afloat
(State Name of Dock.)

Last Survey, No. 3327 Port of Ply.
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stenson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder Pushed
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c. Bottom & coated. 2 New Bathhead Stilton Batt.
She is now in an efficient state
and eligible to remain as classed

Committee's Minute Friday, October, 14th 1881.
Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

LON 667-0005

Loth 6th

Bozian Empire
Cathedral Amekland



© 2021

Lloyd's Register
Foundation