

ANNUAL SURVEYS.

40876

81.

No. in Reg. Book. on the **No.** 47 Survey held at London Date, first Survey Sept 30th Last Survey Tuesday, October, 4th 1881
SS Hankow Master Symington
 Tonnage 2332 Built at Newcastle When built 1873-10
 By whom built Mitchell Owners W Milburn & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock

Last Survey, No. 39985 Port of London Classed 100A/1.81
 SS Lon Wot-77
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Many Rivets renewed
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom is coated
She is now in an efficient state and eligible to remain as classed


Senhouse Martindale.

Committee's Minute Friday, October, 14th 1881.
 Character assigned 100A/1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Lloyd's MC 10.81 Certificate (if required) TRW Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



© 2021

Lloyd's Register Foundation

1000-1299/07