

ANNUAL SURVEYS.

40886

No. 39 Survey held at London Date, first Survey 6th Oct^r Last Survey 6th Oct^r 1881
 No. in on the Screw Ste^r Rainbow Master J. Minchell
 Reg. Book. 39 Net 638 Built at Hundee When built 1871 10 Year. Month.
 Tonnage Gross 1083 Under Dk. 904 By whom built Gourlay Bros. Owners Gen. St^m Nav. Co.
 Port belonging to London Destined Voyage Hamburgh
 If Surveyed Afloat or in Dry Dock Gen. St^m Nav. Co's dry dock Deptford
 (State Name of Dock.)

Last Survey, No. 39460 Port of Lon.

Classed 100 A1 10.80
 S. S. Lon. N^o 2-80

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. paint When put on now

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps 4 N^o

Boats 5 N^o

Masts, Yards, &c.

Condition, how ascertained from deck

Sails 2 Suits good

Anchors, No. of 3 Brs. 1 Stm. 2 Kgs.

Cables 300 fathms. good

Hawsers and Warps 5 N^o

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

Committee's Minute

Tuesday, October 18th 1881.

Character assigned

100

Surveyors to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) 5 Paid 1/11 1881

No. 39 Survey held at London Date, first Survey 6th Oct^r Last Survey 6th Oct^r 1881

No. in on the Screw Ste^r Rainbow Master J. Minchell
 Reg. Book. 39 Net 638 Built at Hundee When built 1871 10 Year. Month.

Tonnage Gross 1083 Under Dk. 904 By whom built Gourlay Bros. Owners Gen. St^m Nav. Co.

Port belonging to London Destined Voyage Hamburgh

If Surveyed Afloat or in Dry Dock Gen. St^m Nav. Co's dry dock Deptford
 (State Name of Dock.)

Last Survey, No. 39460 Port of Lon.

Classed

Years assigned. Character in Register Book.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Cargo and Main Hatchways

Hatches

Committee's Minute

18

Character assigned

Surveyors to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON 667-0020