

ANNUAL SURVEYS.

40888

No. 168 Survey held at Rye Date, first Survey and Last Survey 14th Oct 1881
 No. in on the B^d "Adolphe Laura" Master J. Wicks
 Reg. Book. 168 Net 178 Built at Nantes When built 1867
 Tonnage Gross 178 By whom built Ordreman Owners J C Road
 Under Dk. Port belonging to Rye Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Afloat (State Name of Dock.)

Last Survey, No. 38709 Port of Lon Classed 16A1 Years assigned. 12.79 Character in Register Book.
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Not seen
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Not seen Copper or Y.M. When put on
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. She appears whole seen in good condition and in my opinion may continue as classed

Committee's Minute Tuesday, October 18th 1881 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 16A1 Certificate (if required, to be sent as per margin) Paid 18

No. 168 Survey held at Rye Date, first Survey and Last Survey 18
 No. in on the B^d "Adolphe Laura" Master J. Wicks
 Reg. Book. 168 Net 178 Built at Nantes When built 1867
 Tonnage Gross 178 By whom built Ordreman Owners J C Road
 Under Dk. Port belonging to Rye Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Afloat (State Name of Dock.)

Last Survey, No. 38709 Port of Lon Classed 16A1 Years assigned. 12.79 Character in Register Book.
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Not seen
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Not seen Copper or Y.M. When put on
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. She appears whole seen in good condition and in my opinion may continue as classed

Committee's Minute 18 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 16A1 Certificate (if required, to be sent as per margin) Paid 18

LON667-0024