

# ANNUAL SURVEYS.

40915

No.          Survey held at London Date, first Survey 28<sup>th</sup> Sept<sup>r</sup> Last Survey 29<sup>th</sup> Sept<sup>r</sup> 1881  
 No. in on the Iron Scw. "Avena" Master O. Hellberg  
 Reg. Book. 1455 Tonnage { Net 459 Built at Sunderland When built 1873 Year. 9<sup>th</sup>  
 Gross 728 Under Dk. 548 By whom built Parvison & Co Owners W. Thort'm.  
 Port belonging to Uddvalla Destined Voyage Granton, thence to Copenhagen.  
 If Surveyed Afloat or in Dry Dock In the Bull Head Dry Dock  
 (State Name of Dock.)

Last Survey, No. 27650 Port of Iron  
 Present Condition of the  
 Decks good Treennails good Rivets good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, ~~Pointers~~, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M.          When put on           
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. The bottom has been examined & coated.  
This vessel appears to be eligible to remain as classed.

Committee's Minute Tuesday, October, 25<sup>th</sup> 1881.  
 Character assigned GO DBM Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.          Survey held at          Date, first Survey          Last Survey          18          
 No. in on the          Master           
 Reg. Book.          Tonnage { Net          Built at          When built          Year.          Month.           
 Gross          Under Dk.          By whom built          Owners           
 Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock           
 (State Name of Dock.)

Last Survey, No.          Port of          Classed           
 Present Condition of the  
 Decks          Treennails           
 Waterways          Breasthooks and Stemson           
 Comings          Transoms, Pointers, and Crutches           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings           
 Lower Deck Beams & Fastenings          Ditto ditto at other places           
 Planksheers          Keelsons           
 Sheerstrakes          Clamps and Shelves           
 Topsides          Ceiling           
 Wales          Rudder           
 Plank (Bottom) and Counter          Copper or Y.M.          When put on           
 Caulking of Bottom, Deck, & Waterways           
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches           
 General Observations, Opinion as to Class, &c.         

Committee's Minute 18  
 Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

LON667-0056