

ANNUAL SURVEYS.

40945

No. _____ Survey held at London Date, first Survey 17th Oct^r Last Survey 17th Oct^r 1881
No. in on the Brown Scw. Sr. "Potaro" Master J. Ernst.
Reg. Book. 553 Net 818 Built at Hartlepool When built 1879 Year. 7th Month. _____
Tonnage Gross 1271 By whom built E. Withy & Co Owners Steel, Young & Co
Under Dk. 990 Port belonging to London Destined Voyage Alexandria.
If Surveyed Afloat or in Dry Dock & the Bridge Dry Dock. (State Name of Dock.)

Last Survey, No. 40505 Port of Lon Classed _____ Years assigned. _____ Character in Register Book. 100 A-1
Present Condition of the
Decks good Treennails Rivets good
Waterways D^o Breasthooks and Stemson D^o
Comings D^o Transoms, Pointers, and Crutches D^o
Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
Planksheers D^o Keelsons D^o
Sheerstrakes D^o Clamps and Shelves _____
Topsides D^o Ceiling D^o
Wales D^o Rudder D^o
Plating D^o Copper or Y.M. _____ When put on _____
Plank (Bottom) and Counter D^o Caulking of Bottom, Deck, & Waterways good
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
(If a Steam Ship, state if a Report is also sent on the Machinery _____)
General Observations, Opinion as to Class, &c. The bottom has been examined and coated.
On account of damage: on the starboard side, one plate of the outside plating of the bridge renewed; two frames of the bridge renewed, and one efficiently repaired by working a bosom angle iron.
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.
Committee's Minute _____ Friday November, 4th 1881. J. H. Truscott.
Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
No. in on the _____ Master _____
Reg. Book. _____ Year. _____ Month. _____
Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)
Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
Present Condition of the
Decks _____ Treennails _____
Waterways _____ Breasthooks and Stemson _____
Comings _____ Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
Planksheers _____ Keelsons _____
Sheerstrakes _____ Clamps and Shelves _____
Topsides _____ Ceiling _____
Wales _____ Rudder _____
Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
(If a Steam Ship, state if a Report is also sent on the Machinery _____)
General Observations, Opinion as to Class, &c. _____
Committee's Minute _____ 18 _____
Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____