

# ANNUAL SURVEYS.

No.            Survey held at London Date, first Survey 23<sup>rd</sup> Nov. Last Survey 24<sup>th</sup> Nov. 1881  
 No. in on the S.S. "Gazelle" Master R. Vickers  
 Reg. Book. 137 Net 345 Built at Hartlepool When built 1869 Year. 8 Month.             
 Tonnage Gross 589 Under Dk. 555 By whom built Withy Owners Cory, Lohden & Co.  
 Port belonging to West Hartlepool Destined Voyage Rotterdam  
 If Surveyed Afloat or in Dry Dock Union Dock Hard (State Name of Dock.)

Last Survey, No. 15427 Port of Rue. Classed            Years assigned.            Character in Register Book. A 1 5-81  
S.S. Shl. h-2-77  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c.            Scuppers do Cargo and Main Hatchways Good Hatches do  
 (If a Steam Ship, state if a Report is also sent on the Machinery           )  
 General Observations, Opinion as to Class, &c. This vessel, which was reported to have been aground, has now had bottom examined and found to have sustained no damage. Part of her S.S. h-3 was carried out at Hartlepool in Jan<sup>r</sup> 1881, part at Shields in May 1881, and the Owners intend to complete the survey at Hartlepool a few months hence. The bottom has now been cleaned and coated. She appears to be in good condition and eligible to remain as classed.  
 Committee's Minute Friday, December, 10th, 1881. Joseph Thomson  
Edw. Congdon  
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid            18          

No.            Survey held at            Date, first Survey            Last Survey            18            
 No. in on the            Master             
 Reg. Book.            Year.            Month.             
 Tonnage Net            Built at            When built             
 Gross            By whom built            Owners             
 Under Dk.             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock            (State Name of Dock.)

Last Survey, No.            Port of            Classed            Years assigned.            Character in Register Book.             
 Present Condition of the  
 Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 (If a Steam Ship, state if a Report is also sent on the Machinery           )  
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid            18          

LONG667-0143