

ANNUAL SURVEYS.

No. 38/14/81 Survey held at London Date, first Survey Nov 15 Last Survey Nov 28 1881
No. in SS Ammandale Master J Leish
Reg. Book. 928 Net 1032 Built at Leatherpool When built 1878 Year. 8 Month. 8
Tonnage Gross 1354 By whom built E Withy & Co Owners Steel Young & Co
Under Dk. 1267 Port belonging to London Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock & afloat
(State Name of Dock.)

Last Survey, No. 28155 Port of Iron Classed 100A 10.80
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery No)
General Observations, Opinion as to Class, &c. Bottom be coated
She is now in an efficient state and entitled to remain as classed.

Committee's Minute Friday, December, 16th. 18 81.
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Net Built at When built Year. Month.
Tonnage Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18