

ANNUAL SURVEYS.

(Received at London Office,

12.12.81

No. 40991 Survey held at London Date, first Survey Nov 28 Last Survey Nov 28 1881
 No. in on the SS Menkara Master J. Ballantine
 Reg. Book. 939 Net 1950 Built at Sumberton When built 1878 Year. 7 Month.
 Tonnage Gross 2571 By whom built Senny Owners J. Macneil & P. Senny
 Under Dk. 255 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock (State Name of Dock.)

Last Survey, No. 40634 Port of Lon Classed 100A 7.81
 Present Condition of the
 Decks good Treenails Pivots good
 Waterways good Breasthooks and Stemson good
 Comings good Transoms, Pointers, and Crutches good
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings good Ditto ditto at other places good
 Planksheers good Keelsons good
 Sheerstrakes good Clamps and Shelves good
 Topsides good Ceiling good
 Wales good Rudder good
 Plank (Bottom) and Counter good Copper or Y.M. bottom & counter When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 (If a Steam Ship, state if a Report is also sent on the Machinery yes 15/12)
 General Observations, Opinion as to Class, &c. She is now in an efficient state and eligible to remain as classed

Committee's Minute Tuesday, December, 20th. 1881.
 Character assigned 100A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 18 81

No. 18 Survey held at Calcutta Date, first Survey 1 Last Survey 18
 No. in on the Master
 Reg. Book. Year. Month.
 Tonnage Net Built at When built
 Gross By whom built Owners
 Under Dk. Destined Voyage
 Port belonging to
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. 18 Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned 18
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 18

ANNUAL SURVEYS

McKenna

No.	Survey held at	Date, first survey	Hosts	Guests	Business Topics	Classed
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50

the 18th

No.	Survey held at	Date, first survey	Hosts	Guests	Business Topics	Classed
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100



© 2021
Lloyd's Register
Foundation