

ANNUAL SURVEYS.

40993

(Received at London Office, 19.12.81) 1881

No. Survey held at London Date, first Survey Nov 24 Last Survey Dec 16 1881
 No. in on the S Charlotte Brown Master S M Cookindale
 Reg. Book. 612 Tonnage 1661 Built at Glasgow When built 1874 9
 By whom built C Connell & Co Owners W A Brown
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St & Afloat.

Last Survey, No. 5290 Port of Gls. Classed 100A-1.81.
 Years assigned. SS Man No 1.79. Character in Register Book.
 Present Condition of the Decks Good Treenails Pivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From Hk
 Topsides " Ceiling " Sails Good
 Wales " Rudder " Anchors, No. of 3 Bw. St & Redys Good
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now Cables Part on Hk Good
 Caulking of Bottom, Deck, & Waterways Good Hawsers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated

She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

Committee's Minute Tuesday, December 20th. 1881.
 Character assigned 100A TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid

No. Survey held at London Date, first Survey Nov 30 Last Survey Dec 12 1881
 No. in on the S British Peer Master Greg
 Reg. Book. 802 Tonnage 1428 Built at Belfast When built 1865 1
 By whom built Harland & Wolff Owners But Ship Owners &c
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock & Afloat.

Last Survey, No. 28523 Port of Iron Classed 100A 2.80
 Years assigned. SS Belfast No 3.78 Character in Register Book.
 Present Condition of the Decks Good Treenails Pivets Good
 Waterways " Breasthooks and Stemson " Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches " Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Masts, Yards, &c. "
 Planksheers " Keelsons " Condition, how ascertained From Hk
 Sheerstrakes " Clamps and Shelves " Sails Good
 Topsides " Ceiling " Anchors, No. of 3 Bw. St & Redys Good
 Wales " Rudder Bushed Cables Part on Hk Good
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now Hawsers and Warps "
 Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging "
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated.

She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

Committee's Minute Tuesday, December 20th. 1881.
 Character assigned 100A TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid

Product Price
Christie's

MINIAT. SUBALTA



© 2021

Lloyd's Register
Foundation