

22/12/81

ANNUAL SURVEYS.

41009

(Received at London Office, 23/12/81)

No. 95 on the SS Warwick Castle Survey held at London Date, first Survey Nov 30th Last Survey Dec 1st 18 81
Reg. Book 95 Master A Manchester
Tonnage { Net 1892 Built at Glasgow When built 1877 8
Gross 2257 By whom built Napier Owners S Currie & Co
Under Dk. 2869 Port belonging to London Destined Voyage Cape
If Surveyed Afloat or in Dry Dock James St W by both & afloat
(State Name of Dock.)

Last Survey, No. 40810 Port of Lon

Classed 100A1
Years assigned. 9-81
Character in Register Book.

Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
If a Steam Ship, state if a Report is also sent on the Machinery
General Observations, Opinion as to Class, &c. Bottom & coated.

She is now in an efficient state and respectfully recommend her to remain as classed. The Manager intends to put her through 88 No 1 on her return from her present voyage

Committee's Minute

18

Senhouse Martin

Character assigned

100A1

TRM

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 2 on the 2 of Survey held at 2 of Date, first Survey 2 of Last Survey 18
Reg. Book 2 of Master 2 of
Tonnage { Net 2 of Built at 2 of When built 2 of
Gross 2 of By whom built 2 of Owners 2 of
Under Dk. 2 of Port belonging to 2 of Destined Voyage 2 of
If Surveyed Afloat or in Dry Dock 2 of
(State Name of Dock.)

Last Survey, No.

Port of

Classed

Present Condition of the
Decks Good Treenails Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
If a Steam Ship, state if a Report is also sent on the Machinery
General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LOW667-0176

Marmuk Castle

ANNUAL SURVEYS



© 2021

Lloyd's Register
Foundation