

ANNUAL SURVEYS.

4 10 30

16/12/81

No. 3 Survey held at London Date, first Survey Nov 23^d Last Survey Dec 16th 18 81
 No. in on the SS Dryburgh Abbey Master J Forbes
 Reg. Book. 3 Net 1481 Built at Newcastle When built 1881 Year. 4 Month. 4
 Tonnage Gross 2264 Under Dk. 2207 By whom built W Richardson Owners Wood Bros
 Port belonging to Liverpool Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Blackwall Point by Mr Vaffant
 (State Name of Dock.)

Last Survey, No. 15403 Port of Newcastle Classed 100A. 6.81
 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Rivets	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Boats <u>4</u>	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Keelsons	<u>"</u>	Clamps and Shelves	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ceiling	<u>"</u>	Rudder	<u>"</u>	Condition, how ascertained	<u>From Stk</u>
Planksheers	<u>"</u>	Copper or Y.M. <u>Cortice</u>	<u>When put on</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches	<u>"</u>
Fopsides	<u>"</u>						
Wales	<u>"</u>						
Plank (Bottom) and Counter	<u>"</u>						

General Observations, Opinion as to Class, &c. Being a barge being on shore many of the bolts in the bottom bulkhead made good and some rivets in the stern part & Rudder renewed bottom ke coated she is now in an efficient state and eligible to remain as classed
 Committee's Minute Friday, December, 23rd 18 81.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping. J B W
 Certificate (if required, to be sent as per margin) 57 - Paid 23/1/82

No. also Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Net _____ Built at _____ When built _____ Year. _____ Month. _____
 Tonnage Gross _____ Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. Character in Register Book.

Present Condition of the Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors, No. of	
Fopsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper or Y.M. _____	<u>When put on</u>	Standing and Running Rigging	
		Caulking of Bottom, Deck, & Waterways			
Engine Room Skylights		Coal Bunkers, Openings, Lids, &c.		Scuppers	
General Observations, Opinion as to Class, &c.				Cargo and Main Hatchways	

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

Form No. 2 for Repairs. - 1,000 - 15/6/81.



Brynmor Abbey

20/10/18

RYNIVRUS JAUNIA



© 2021

Lloyd's Register
Foundation