

# ANNUAL SURVEYS.

41039

No. 1403 Survey held at London Date, first Survey Sept 30th Last Survey Oct 14th 1881  
 No. in on the SS Courland Master Young  
 Reg. Book. 1403 No. 803 Built at Glasgow When built 1872 Year. 1 Month.  
 Tonnage 1241 Gross 1241 Under Dk. 1221 By whom built Napier & Co Owners Leith Hull & Hamburg St  
 Port belonging to Leith Destined Voyage Coast  
 If Surveyed Afloat or in Dry Dock Greens Dyk St & afloat (State Name of Dock.)

Last Survey, No. 40625 Port of Lon

Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Kinksheers " Keelsons "  
 Berstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 (If a Steam Ship, state if a Report is also sent on the Machinery Yes No 27/81)  
 General Observations, Opinion as to Class, &c. Bottom & counter.  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, January, 3rd. 1882.  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) 18

No. 1403 Survey held at London Date, first Survey Sept 30th Last Survey Oct 14th 1881  
 No. in on the SS Courland Master Young  
 Reg. Book. 1403 No. 803 Built at Glasgow When built 1872 Year. 1 Month.  
 Tonnage 1241 Gross 1241 Under Dk. 1221 By whom built Napier & Co Owners Leith Hull & Hamburg St  
 Port belonging to Leith Destined Voyage Coast  
 If Surveyed Afloat or in Dry Dock Greens Dyk St & afloat (State Name of Dock.)

Last Survey, No. 40625 Port of Lon Classed 100A  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Kinksheers " Keelsons "  
 Berstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 (If a Steam Ship, state if a Report is also sent on the Machinery Yes No 27/81)  
 General Observations, Opinion as to Class, &c. Bottom & counter.  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute 18  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) 18

LON667-0219



ANNUAL SURVEY

1871

Survey held at

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871

1871