

Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 20/1/82)

No. in Reg. Book.

Survey held at London

Date, first Survey

and

Last Survey Jan: 17th 1882

699 on the Machinery of the S.S. "Baconshire"

(Number of Visits 1)

Tonnage, Gross 1902

Ditto, Net 1241

Diameter of Cylinder 36" + 66"

Length of Stroke 42"

Pressure of Steam 70 lbs.

Registered Horse Power 275

Built at Glasgow

Owners S. S. Lintin & Co.

Engines made by Lon. & Glas. Co.

Boilers made by Ditto

If Surveyed Afloat or in Dry Dock Albert Dry dock
(State name of Dock.)

When built 1878

Port belonging to London

When made 1878

When made 1878

Classed 100 A 1

Last Survey No.

Port

Lloyds M.C. 279

Particulars of Repairs and Examination For Annual Survey -

(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller found to be sound & the tail shaft a good working fit in stern bush.

General Observations, Opinion, and Recommendation :— As far as seen this vessel appears eligible to remain as classed

Entry or Registering Fee... £ : :

Survey Fee (per Section 28) ... £ — : — : received by me, }


Certificate (if required) ... £ : : 188 }

(Travelling Expenses, if any, £)

Committee's Minute Tuesday, January, 24th. 1882.

Assigned

Geo. E. Milnerison.
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LONG667-0295

It is submitted that this vessel
is eligible to remain as
classified

M 20/1/82



© 2021

Lloyd's Register
Foundation