

# ANNUAL SURVEYS.

41170

No. 5 Survey held at London Date, first Survey Jan 31 Last Survey July 7 1882  
 No. in on the Reg. Book. SS Oakdale Master J. F. Cabre  
 Tonnage 857 Net 1408 Gross 1054 Under Dk. Built at Hartlepool When built 1878 3 Month.  
 By whom built Steel Young & Co Owners London Destined Voyage Permanently to Brisbane  
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock & afloat (State Name of Dock.)

Last Survey, No. 40407 Port of London Classed 100 A 4.81  
 Present Condition of the Decks good Treenails Rivets good  
 Waterways good Breasthooks and Stemson good  
 Comings good Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Lower Deck Beams & Fastenings good Ditto ditto at other places good  
 Planksheers good Keelsons good  
 Sheerstrakes good Clamps and Shelves good  
 Topsides good Ceiling good  
 Wales good Rudder good  
 Plank (Bottom) and Counter good Copper or Y.M. Bottom coated When put on now  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. Bottom & coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, February, 17th 1882. Senhouse Martindale  
 Character assigned 100 A 4.81 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in on the Reg. Book. \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Under Dk. \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 Port belonging to \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18



The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.