

ANNUAL SURVEYS.

No. 433 Survey held at London Date, first Survey Jan 30 Last Survey Feb 17 18 82
 on the BR Spirit of the Dawn Master S Judd
 Reg. Book. 433 Net 672 Built at Sunderland When built 1867 Month. 3
 Tonnage Gross 716 Under Dk. 653 By whom built Arnold Owners J Bell
 Port belonging to Liverpool Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Blackwall Quay by the afloat.
 (State Name of Dock.)

Last Survey, No. 27581 Port of Liv

Classed

Years assigned. Character in Register Book.

*A/

4.81

P.S. No. 3-81

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>Now</u>	
		Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Coal Bunkers, Openings, Lids, &c.	
General Observations, Opinion as to Class, &c.	<u>Bottom & counter. She is now in an efficient state and respectfully recommended her to remain as classed. A third boiler anchor now supplied. 21 but 300-0. Tested to 22 tons 3 but 170. River Wear Boiling House dated Jan 11th 1876. The 2 other boiler anchors larger than the new one but the marks signed J. Hartnup and weights could not be made out being corroded by salt water.</u>		

Committee's Minute

Tuesday, February, 21st 1882.

Senhouse Martindale.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 791 Survey held at London Date, first Survey Jan 23 Last Survey Feb 18 82
 on the S British Enterprise Master Carnell
 Reg. Book. 791 Net 1640 Built at Stockton When built 1876 Month. 10
 Tonnage Gross 1686 Under Dk. 1550 By whom built Richardson & Sons Owners Brit Ship Owners &c
 Port belonging to Liverpool Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens by Dock & afloat
 (State Name of Dock.)

Last Survey, No. 28315 Port of Liv

Classed

Years assigned. Character in Register Book.

100-A 11.80.

58 Lon Wp. 80

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>Now</u>	
		Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Engine Room Skylights		Coal Bunkers, Openings, Lids, &c.	
General Observations, Opinion as to Class, &c.	<u>Bottom & counter. She is now in an efficient state and eligible to remain as classed.</u>		

Committee's Minute

Tuesday, February, 21st 1882.

Senhouse Martindale

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON667-0403