

ANNUAL SURVEYS.

41188

No. 433 Survey held at London Date, first Survey Jan'y 27 Last Survey Feb'y 2 1882
 No. in on the SS Glenavon Master A Taylor
 Reg. Book. 433 Net 1936 Built at Glasgow When built 1881 2.
 Tonnage Gross 2985 By whom built Sen & Glas Owners M Gregor how & Co
 Under Dk. 2656 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Greens Dry Dock (State Name of Dock.)

Last Survey, No. 40809 Port of London

Classed 100 A. 1. 8. 81.

Present Condition of the
 Decks good Treenails Pivots good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. This vessel had touched some hard substance on the upper part of the Port Bilge making an unsightly indent in the upper edge of a plate. The indented part has been now cut out & a piece well fitted in & a doubling plate on the inside well through rivetted. She is now in an efficient state and eligible to remain as classed.

Committee's Minute

Tuesday, February, 21st 1882.

Character assigned

100 A. 1

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built
 Tonnage Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of

Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute

Tuesday, February, 21st 1882.

Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON667-0405

Committee's Minutes

General Observations, Minutes, and Resolutions

1. On Motion, Resolved, That the Committee do hereby recommend the following Resolutions to be adopted by the Association:

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

2. On Motion, Resolved, That the Committee do hereby recommend the following Resolutions to be adopted by the Association:

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

Committee's Minutes


General Observations, Minutes, and Resolutions

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

Resolved, That the Association do hereby recommend the following Resolutions to be adopted by the Association:

Glenview

ANNUAL SURVEYS



© 2021

Lloyd's Register Foundation