

# ANNUAL SURVEYS.

41209

(Received at London Office,)

No.            Survey held at London Date, first Survey July 27<sup>th</sup> Last Survey July 28<sup>th</sup> 1882  
 No. in on the S Yankand Master J Gallender  
 Reg. Book. 16 Net 131 Built at Barron When built 1877 Year. 1 Month.             
 Tonnage Gross 1352 By whom built Barron S.C. Owners E Bates & Son  
 Under Dk. 1248 Port belonging to Liverpool Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St.  
(State Name of Dock.)

Last Survey, No. 5161 Port of Wpt

Classed 100A 1 5.81  
 SS Wpt 11.81

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>from St</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of 3 Pro. <u>St &amp; Redgs</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Part on St</u> <u>Good</u>
Wales <u>"</u>	Rudder <u>Brushed</u> <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>          </u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u> Hatches <u>"</u>

Coal Bunkers, Openings, Lids, &c.            Scuppers Good  
 General Observations, Opinion as to Class, &c. Bottom & coated  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, March, 3rd. 1882. Senhouse Martindale  
 Character assigned 100A 1 JRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid 18

No.            Survey held at London Date, first Survey Jan 15<sup>th</sup> Last Survey Jan 20<sup>th</sup> 1882  
 No. in on the Star of Denmark Master Willis  
 Reg. Book. 1073 Net 598 Built at Belfast When built 1863 Year. 6 Month.             
 Tonnage Gross 998 By whom built Harland Owners J Cruz & Co  
 Under Dk. 971 Port belonging to Belfast Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Greens try St Vapour  
(State Name of Dock.)

Last Survey, No. 40413 Port of Louv

Classed A 1 5.81  
 SS Louv 11.81  
 S.S. No. 3-76

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>from St</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of 3 Pro. <u>St &amp; Redgs</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Part on St</u> <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>          </u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u> Hatches <u>"</u>

Coal Bunkers, Openings, Lids, &c.            Scuppers Good  
 General Observations, Opinion as to Class, &c. Bottom & coated  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, March, 3rd. 1882. Senhouse Martindale  
 Character assigned A 1 JRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid 18

(Form No. 5 for Annual Survey, when there are no repairs. 4100-6/12/80.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 (Insert Character precisely as in Register Book.)



LON667-0427