

ANNUAL SURVEYS.

41255

No. Survey held at London Date, first Survey July 7 Last Survey July 27th 1882
 No. in on the SS Garth Castle Master M. P. Webster
 Reg. Book. 111 Net 2381 Built at Glasgow When built 1880 Year. 12 Month.
 Tonnage Gross 3705 Under Dk. 3537 By whom built J. Eldon Owners J. Currie & Co.
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Names I N by Mr J after
 (State Name of Dock.)

Last Survey, No. 40582 Port of London

Classed 100A-11.81 Years assigned. Character in Register Book.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Pine</u>	<u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Cu</u> When put on <u>new</u>	<u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	<u>"</u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. Bottom &c. coated
She is now in an efficient state
and eligible to remain as classed.
Chain cables ranged in the bottom of by boat
for the Government surveys & examined by me 300 fathom

Committee's Minute Tuesday, March, 14th 1882. Senhouse Martin

Character assigned 100A-1 Surveyor to Lloyd's Register of British and Foreign Shipping.

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.


Decks <u> </u>	Treenails <u> </u>	<u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	<u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	<u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	<u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	<u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	<u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	<u> </u>
Topsides <u> </u>	Ceiling <u> </u>	<u> </u>
Wales <u> </u>	Rudder <u> </u>	<u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	<u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	<u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18



LONGG67-0481