

23/2/82

ANNUAL SURVEYS.

41256

No. 769 Survey held at London Date, first Survey Feb 21st Last Survey Feb 21st 1882
No. in on the SS Soudown Castle Master H. Kiddle
Reg. Book. 769 Net 1616 Built at Glasgow When built 1876 10 Month.
Tonnage Gross 2472 By whom built J & G Thomson Owners J Skinner & Co
Under Dk. 2308 Port belonging to Glasgow Destined Voyage China &c
If Surveyed Afloat or in Dry Dock Royal Albert Dock afloat Port Basin.
(State Name of Dock.)

Last Survey, No. 732 Port of Ant
Present Condition of the
Decks Good Treenails Rivets Good
Waterways Good Breasthooks and Stenson Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. New Life Boat supplied, 2 damaged boats repaired, 6 boats chocks, skids, davit &c repaired and renewed where required, 6 boats. She is now in an efficient state and eligible to remain as classed. Antwerp Report attached.

Committee's Minute Tuesday, March, 14th 1882. Senhouse Martindale
Character assigned TRM 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) 18

No. 769 Survey held at London Date, first Survey Feb 21st Last Survey Feb 21st 1882
No. in on the SS Soudown Castle Master H. Kiddle
Reg. Book. 769 Net 1616 Built at Glasgow When built 1876 10 Month.
Tonnage Gross 2472 By whom built J & G Thomson Owners J Skinner & Co
Under Dk. 2308 Port belonging to Glasgow Destined Voyage China &c
If Surveyed Afloat or in Dry Dock Royal Albert Dock afloat Port Basin.
(State Name of Dock.)
Last Survey, No. 732 Port of Ant Classed 100A1 7.81
Present Condition of the
Decks Good Treenails Rivets Good
Waterways Good Breasthooks and Stenson Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Good When put on Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. New Life Boat supplied, 2 damaged boats repaired, 6 boats chocks, skids, davit &c repaired and renewed where required, 6 boats. She is now in an efficient state and eligible to remain as classed. Antwerp Report attached.
Committee's Minute 18
Character assigned TRM 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) 18