

ANNUAL SURVEYS.

47322

(Received at London Office, REGISTERED 1882)

No. 792 Survey held at London Date, first Survey March 22 Last Survey March 28 1882

No. in on the San Juan Maria Erasmus Wilson Master Bond

Reg. Book. 792 Tonnage { Net 497 Built at Harlepool When built 1876 Month. 3
Gross 825
Under Dk. 146 By whom built E. Withy and Co Owners J. Clarke and Co.

Port belonging to London Destined Voyage not fixed

If Surveyed Afloat or in Dry Dock of Messrs. Hitchen's Union dock
(State Name of Dock.)

Last Survey, No. 40529 Port of London

Classed 90 A.1 Years assigned. 5.81 Character in Register Book.

Present Condition of the

Decks <u>good</u>	Treenails <u>fair</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the Openings <u>good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Condition, how ascertained <u>from deck</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Sails <u>complete</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Anchors, No. of <u>2 1/2 2 1/2</u>
Topsides <u>do</u>	Ceiling <u>good</u>	Cables <u>not ranged</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>good</u>
Plank (Bottom) and Counter <u>do</u>	Copper or Y.M. <u>do</u> When put on <u>do</u>	Standing and Running Rigging <u>good</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	
Coal Bunkers, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
Hatches <u>good</u>		

General Observations, Opinion as to Class, &c. Being in good condition and found to be in my opinion
able to remain as classed. Now done the bottom cleaned & treated

Committee's Minute Tuesday, April, 4th 1882.

Character assigned 90 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master

Reg. Book. Tonnage { Net Built at When built Year. Month.
Gross
Under Dk. By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the

Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Standing and Running Rigging <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18