

ANNUAL SURVEYS.

41349

No. 52 Survey held at London Date, first Survey 31st March Last Survey 5th April 1882
 No. in on the Iron Barge "Natal" Master A. Tytler.
 Reg. Book. 52 Tonnage { Net 446 Built at Aberdeen When built 1876 Year. 12th
 { Gross 459 By whom built A. Hall & Co Owners J. T. Rennie & Son.
 { Under Dk. 393 Port belonging to Aberdeen Destined Voyage Natal.
 If Surveyed Afloat or in Dry Dock In the Ratcliff Dry Dock.
(State Name of Dock.)

Last Survey, No. 40306 Port of London Classed L.L. Don. No-1-81 Years assigned. 100 A.1 Character in Register Book. 4.81
 Present Condition of the Decks good Treenails Rivets good
 Waterways D^o Breasthooks and Stenson D^o
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
 Planksheers D^o Keelsons D^o
 Sheerstrakes D^o Clamps and Shelves D^o
 Topsides D^o Ceiling D^o
 Wales D^o Rudder D^o
 Plank (Bottom) and Counter D^o Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good.
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.
The bottom has been examined & coated. The rudder pintles rebushed. Vessel surveyed with part outward cargo in the fore part of the hold. She is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute Tuesday, April, 11th 1882. J. H. Truscott.
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____ By whom built _____ Owners _____
 { Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
(If a Steam Ship, state if a Report is also sent on the Machinery)

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 1 for Annual Survey, when there are no repairs. 4100-6, 12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

