

ANNUAL SURVEYS.

41379

(Received at London Office, RECEIVED 20th APL. 82.)

No. _____ Survey held at London Date, first Survey April 11th Last Survey April 11th 1882
 No. in on the SS Camorta Master S J Bergmann
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage { Net 1578 Built at Glasgow When built 1880 11
 Gross 2094 By whom built A J Inglis Owners A Gray & S Sawe
 Under Dk. 1891 Port belonging to Glasgow Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Albert by Holt
(State Name of Dock.)

[Handwritten Signature]

Last Survey, No. 40443 Port of Lon Classed 100A. 5.81
Years assigned. Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained <u>From St</u>
Planksheers _____	Keelsons _____	Sails <u>Good</u>
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of <u>3 No. St & Redgs</u>
Topsides _____	Ceiling _____	Cables <u>Part on St</u> <u>Good</u>
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. <u>Covered</u> When put on <u>now</u>	Standing and Running Rigging _____
Engine Room Skylights <u>Good</u> Coal Bunkers, Openings, Lids, &c. <u>Good</u> Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches _____	Caulking of Bottom, Deck, & Waterways <u>Good</u>	

General Observations, Opinion as to Class, &c. Bottom to coated
She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, April 21st. 1882.
 Character assigned 100A. 5.81 J. W. [Signature] Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Caulking of Bottom, Deck, & Waterways _____	

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 4 for Annual Survey, when there are no repairs, 4000-6/12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

