

41379
Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 14. 4. 82.)
No. in Reg. Book. Survey held at London Date, first Survey _____ and Last Survey Apr. 12th 1882
144 on the Machinery of the S. S. "Camorta" (Number of Visits 1)
Tonnage, Gross 2094 Built at Glasgow When built 1880
Ditto, Net 1589 Owners A. Gray & C. S. Dawes Port belonging to Glasgow
Diameter of Cylinder 34" + 60" Engines made by A & J. Inglis When made 1880
Length of Stroke 45" Boilers made by Ditto When made 1880
Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock Alb. D. Dr. (State name of Dock.)
Registered Horse Power 200 Classed 100A1
Last Survey No. _____ Port Lloyd M.C. 1.81.

Particulars of Repairs and Examination For Annual Survey
(State cause of Repairs.)
Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller & its connections sound & the tail shaft a good working fit in Stern Bush. Examined High Pressure slide valve & found them to be in good condition.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

Entry or Registering Fee... £ : :
Survey Fee (per Section 28) ... £ : : received by me, }
Certificate (if required) ... £ : : 188 }
(Travelling Expenses, if any, £ _____)

Committee's Minute _____ Friday, April, 21st, 1882
Assigned _____
Lloyd's Register Foundation