

ANNUAL SURVEYS.

41424

No. 518 Survey held at London Date, first Survey 1878 Last Survey 13th April 1882
 No. in Reg. Book. 518 on the Sam S. S. "Leta" Master Lucker
 Tonnage 612 Net 970 Gross 942 Under Dk. Built at Stockton When built 1878 1 Month.
 By whom built M. Pearce & Owners A. Cloake
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock West India dry Dk.
(State Name of Dock.)

Last Survey, No. 40653 Port of London Classed 100A1
 Years assigned. 7.81 Character in Register Book.
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways --- Breasthooks and Stimson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder partly bucked
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1878
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Bottom painted. Rudder partly bucked. She is now in good condition and in my opinion may continue as classed survey not deferred until her return


After Ballast Tank contains 8 Tons Fore Tank 100 Tons

Committee's Minute Friday, 5th. May, 18 82. Wm. C. Davy
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in Reg. Book. _____ on the _____ Master _____
 Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stimson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid _____ 18 _____



Insert Character precisely as in Register Book.