

ANNUAL SURVEYS.

(Received at London Office, 4/5/82)

No. 41428 Survey held at London Date, first Survey April 11 Last Survey May 1st 1882
No. in on the BR Star of Erin Master Coulter
Reg. Book. 1016 Net 949 Built at Belfast When built 1862 Month. 10
Tonnage 949 By whom built Harland Owners J. Barry & Co
Under Dk. 919 Port belonging to Belfast Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Greens St & Afloat
(State Name of Dock.)

Last Survey, No. 40579 Port of LowClassed A Years assigned. 1 Character in Register Book. 6.81

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Condition, how ascertained	<u>From St</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors, No. of <u>3 Bcs. St & Kedge</u>	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables <u>Part on St</u>	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. <u>Covered</u> When put on <u>now</u>		Standing and Running Rigging	<u>"</u>
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>		
Scuppers	<u>Good</u>				
Cargo and Main Hatchways	<u>Good</u>				
Hatches	<u>"</u>				

(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

Bottom is covered
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday, 5th. May, 18 82.Character assigned ASenhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 41428 Survey held at London Date, first Survey April 6 Last Survey April 28th 1882
No. in on the S Ben Voirlach Master Douglas
Reg. Book. 297 Net 1474 Built at Glasgow When built 1878 Month. 12
Tonnage 1504 By whom built Barclay Owners Watson Bros
Under Dk. 1312 Port belonging to Glasgow Destined Voyage Australia
If Surveyed Afloat or in Dry Dock Albert St & Afloat
(State Name of Dock.)

Last Survey, No. 40328 Port of LowClassed 100A Years assigned. 4.81 Character in Register Book. 4.81

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Condition, how ascertained	<u>From St</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors, No. of <u>3 Bcs. St & Kedge</u>	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables <u>Part on St</u>	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. <u>Covered</u> When put on <u>now</u>		Standing and Running Rigging	<u>"</u>
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>		
Scuppers	<u>Good</u>				
Cargo and Main Hatchways	<u>Good</u>				
Hatches	<u>"</u>				

(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

Bottom is covered
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday, 5th. May, 18 82.Character assigned 100ASenhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18