

# ANNUAL SURVEYS.

41430

No. \_\_\_\_\_ Survey held at London Date, first Survey April 6<sup>th</sup> Last Survey April 27<sup>th</sup> 1882  
 No. in on the S The Lord Warden Master Coake  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net 1237 Built at Sunderland When built 1862  
 Gross 1237 By whom built Pale Hay St Owners R & H Green  
 Under Dk. 1087  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Greens by St & afloat  
(State Name of Dock.)

Last Survey, No. 40613 Port of London Classed 15A1 7.81  
 Character in Register Book. Cent 1m sec 7-10 yrs

|  |   |   |
|--|---|---|
| Present Condition of the Decks <u>good</u> | Treenails <u>good</u>                         | Windlass and Capstan <u>good</u>                        |
| Waterways <u>"</u>                         | Breasthooks and Stemson <u>"</u>              | Pumps <u>"</u>  |
| Comings <u>"</u>                           | Transoms, Pointers, and Crutches <u>"</u>     | Boats <u>"</u>  |
| Upper Deck Beams & Fastenings <u>"</u>     | Timbers of the Frame at the Openings <u>"</u> | Masts, Yards, &c. <u>new upper main &amp; fore yard</u> |
| Lower Deck Beams & Fastenings <u>"</u>     | Ditto ditto at other places <u>"</u>          | Condition, how ascertained <u>from St</u>               |
| Planksheers <u>"</u>                       | Keelsons <u>"</u>                             | Sails <u>good</u>                                       |
| Sheerstrakes <u>"</u>                      | Clamps and Shelves <u>"</u>                   | Anchors, No. of <u>3 Bbs. St &amp; Reddy</u>            |
| Topsides <u>"</u>                          | Ceiling <u>"</u>                              | Cables <u>Part on deck</u>                              |
| Wales <u>"</u>                             | Rudder <u>"</u>                               | Hawsers and Warps <u>"</u>                              |
| Plank (Bottom) and Counter <u>"</u>        | Copper or Y.M. _____ When put on _____        | Standing and Running Rigging <u>"</u>                   |
| Engine Room Skylights _____                | Caulking of <u>Patched now</u>                | Cargo and Main Hatchways <u>good</u>                    |
| Coal Bunkers, Openings, Lids, &c. _____    | Bottom, Deck, & Waterways <u>good</u>         | Hatches <u>"</u>  |
| Scuppers <u>good</u>                       |   |   |

General Observations, Opinion as to Class, &c. Yellow Metal Patches & Bottom sighted  
She is now in an efficient state  
and eligible to remain as classed

Committee's Minute Friday, 5th. May, 18 82.  
 Character assigned Class 10A  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Character in Register Book. \_\_\_\_\_

|   |  |                                    |
|---|--|------------------------------------|
| Present Condition of the Decks _____    | Treenails _____                            | Windlass and Capstan _____         |
| Waterways _____                         | Breasthooks and Stemson _____              | Pumps _____                        |
| Comings _____                           | Transoms, Pointers, and Crutches _____     | Boats _____                        |
| Upper Deck Beams & Fastenings _____     | Timbers of the Frame at the Openings _____ | Masts, Yards, &c. _____            |
| Lower Deck Beams & Fastenings _____     | Ditto ditto at other places _____          | Condition, how ascertained _____   |
| Planksheers _____                       | Keelsons _____                             | Sails _____                        |
| Sheerstrakes _____                      | Clamps and Shelves _____                   | Anchors, No. of _____              |
| Topsides _____                          | Ceiling _____                              | Cables _____                       |
| Wales _____                             | Rudder _____                               | Hawsers and Warps _____            |
| Plank (Bottom) and Counter _____        | Copper or Y.M. _____ When put on _____     | Standing and Running Rigging _____ |
| Engine Room Skylights _____             | Caulking of _____                          | Cargo and Main Hatchways _____     |
| Coal Bunkers, Openings, Lids, &c. _____ | Bottom, Deck, & Waterways _____            | Hatches _____                      |
| Scuppers _____                          |  |                                    |

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_



L04668-0130