

ANNUAL SURVEYS.

41438

(Received at London Office, 1882)

No. 1 Survey held at London Date, first Survey March 21 Last Survey April 26th 1882
 No. in on the SS Elizabeth Martin Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage 440 Net 805 Built at Glasgow When built 1872
 Gross 1246 By whom built R Napier & Co Owners A Currie
 Under Dk. 1226 Port belonging to Greenock Destined Voyage Vessel laid up
 If Surveyed Afloat or in Dry Dock Greens Bk & afloat
(State Name of Dock.)

Last Survey, No. 2833 / Port of Green Classed 100A-1 10.81
 SS Lin No 2-80
 Present Condition of the
 Decks good Treenails Rivets good
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. coated When put on now
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained from H
 Sails _____
 Anchors, No. of 3 Pro. 82 & Redge
 Cables Part on H
 Hawfers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. Bottom be coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, 9th May, 18 82. Senhouse Martin & Co
 Character assigned 100A-1 TBM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 5/ Paid MMS 18 4/6 82

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the
 Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawfers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18____

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 (If a No. 2 for Annual Survey, when there are no repairs, 4000-6, 12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

