

ANNUAL SURVEYS.

No. 432 Survey held at London Date, first Survey 31st Mar Last Survey 17th Apr 1882
No. in on the Sm S S "Glenartney" Master H. Auld
Reg. Book. 432 Tonnage { Net 1400 Built at Glasgow When built 1873 Year. 9 Month. 9
Gross 2143 By whom built Ln Glas Co Owners McGee & Co
Under Dk. 2065 Port belonging to Glasgow Destined Voyage China
If Surveyed Afloat or in Dry Dock Poplar dry dock & afloat
(State Name of Dock.)

Last Survey, No. 40568 Port of Lon Classed 100A1 10-81
Present Condition of the Decks Good Treenails Good Rivets Good
Waterways Good Breasthooks and Stemon Good
Comings Good Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
Planksheers Good Keelsons Good
Sheerstrakes Good Clamps and Shelves Good
Topsides Good Ceiling Good
Wales Good Rudder Good
Plank (Bottom) and Counter Good Copper or Y.M. Good When put on 1873
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery)
General Observations, Opinion as to Class, &c. Bottom repainted. She is now in good condition and in my opinion may continue as Classed

Committee's Minute Tuesday, 9th May, 1882.
Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping. W. E. Davey
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage { Net Built at When built Year. Month.
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Present Condition of the Decks Treenails
Waterways Breasthooks and Stemon
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18