

ANNUAL SURVEYS.

4 14 46

No. 216 on the Iron B^d "Irvine" Survey held at London Date, first Survey 7 Last Survey 25th Apr 1882
 Master W. Fernie
 Tonnage Net 655 Built at Swansea When built 1867 Month 5
 Gross 655 By whom built Doeferd Owners D. Hunter
 Under Dk. 627
 Port belonging to Ayr Destined Voyage Poplar dry Dk
 If Surveyed Afloat or in Dry Dock Poplar dry Dk
 (State Name of Dock.)

Last Survey, No. 26212 Port of London
 Present Condition of the
 Hulls Good Greenails Rivets Good
 Waterways Good Breasthooks and Stems
 Masts Good Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Good Ditto ditto at other places
 Tanksheers Good Keelsons
 Berthstrakes Good Clamps and Shelves
 Sides Good Ceiling
 Deck Good Rudder
 (Bottom) and Counter Good Copper or Y.M. Cement When put on 1876
 Caulking of Good Bottom, Deck, & Waterways
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom painted. She is now in good condition and in my opinion eligible to continue as classed

Committee's Minute Friday, 12th May, 1882.
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 71 on the Iron S. "Pleione" Survey held at London Date, first Survey 2nd May Last Survey 5th May 1882
 Master C. N. Renaut
 Tonnage Net 1092 Built at Glasgow When built 1876 Month 9
 Gross 1139 By whom built A. Stephenson Owners Shaw Savill & Co
 Under Dk. 984
 Port belonging to Southampton Destined Voyage Wellington, N.Z.
 If Surveyed Afloat or in Dry Dock Rugg's dry Dk
 (State Name of Dock.)

Last Survey, No. 40587 Port of London
 Present Condition of the
 Hulls Good Greenails Rivets Good
 Waterways Good Breasthooks and Stems
 Masts Good Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Good Ditto ditto at other places
 Tanksheers Good Keelsons
 Berthstrakes Good Clamps and Shelves
 Sides Good Ceiling
 Deck Good Rudder
 (Bottom) and Counter Good Copper or Y.M. Cement When put on 1876
 Caulking of Good Bottom, Deck, & Waterways
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom painted. Rudder pintles broken. She is now in good condition and in my opinion eligible to continue as classed

Committee's Minute Friday, 12th May, 1882.
 Character assigned 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18