

Report of Survey for Repairs of Engines and Boilers.

41455

No. _____ (Received at London Office, _____)
 No. in Reg. Book. *306* Survey held at *London* Date, first Survey *24 April* Last Survey *1 May 1881*
 on the Machinery of the *S. S. Rhone* (Number of Visits *4*)
 Tonnage, Gross *1343* Built at *Sunderland* When built *1868*
 Ditto, Net *868* Owners *Westcott & Laurence* Port belonging to *London*
 Diameter of Cylinder *30 + 5/4* Engines made by *Millwall & Co* When made *1871*
 Length of Stroke *34* Boilers made by _____ When made *1871*
 Pressure of Steam *55* If Surveyed Afloat or in Dry Dock *Millwall Dry Dock* (State name of Dock.)
 Registered Horse Power *200* Classified *90 A1*
 Last Survey No. _____ Port *W.C. 480*

Particulars of Repairs and Examination *Special Survey No 3.*
 Examined *Leucocets & connections & found them in good condition*
The propeller has been removed & refitted
The cylinders & slides & valves were in good condition.
The safety valves are loaded to 55 lbs.
The boilers were found to be in good condition
The pumps were opened out & found to be in good condition

General Observations, Opinion, and Recommendation:— *The machinery of this vessel appears to be in a safe working condition & is in my opinion eligible to have the notification B + M S. 5. 82. recorded in the Register Book.*

Entry or Registering Fee... £ *1* : *10* :
 Survey Fee (per Section 28) ... £ *3* : *3* : — received by me, *CB*
 Certificate (if required) ... £ : *5* : — *17/5/ 1882*

Committee's Minute *Tuesday, 16th May, 1882.*
 Assigned *B + M S. 5, 82*
 Engineer, Surveyor to Lloyd's Register of British & Foreign Shipping.

 Lloyd's Register Foundation
 LON 668-0156

Repairs and Examinations, to be clearly stated.

(Insert Character precisely as in the Register Book.)

It is submitted that this vessel is eligible to have the notification B + M S. 5.82. recorded subject to the main boilers being resurveyed as per Rule

W.S.
4/5/82.

