

ANNUAL SURVEYS.

41477

No. 506 Survey held at London Date, first Survey April 24 Last Survey April 24 1882
 No. in on the Reg. Book. 506 Master _____
 Tonnage { Net 1411 Built at Glasgow When built 1871 Month. 8
 Gross 2159 By whom built Smith & Glasco Owners M. Ferguson & Co.
 Under Dk. 2085 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Greenock by Mr
(State Name of Dock.)

Last Survey, No. 40507 Port of London Classed 100A-5.8
Years assigned. Character in Register Book.
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From SK
 Topsides " Ceiling " Sails good
 Wales " Rudder " Anchors, No. of 3 No. 11 & 12 lbs
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on now Cables Carbon 8/4 good
 Caulking of Bottom, Deck, & Waterways good Hawsers and Warps "
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated, she is now in an efficient state and eligible to remain as classed

Committee's Minute Friday, 19th May, 1882. Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the Reg. Book. _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____ Month. _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

