

ANNUAL SURVEYS.

(Received at London Office, 1.6.82)

No. Survey held at London Date, first Survey 16th May Last Survey 17th May 1882
 No. in on the Siron Ship "Suckland" Master M. Wougal
 Reg. Book. 1392 Year. Month.
 Tonnage { Net 1245 Built at Port Glasgow When built 1874
 Gross 1308 By whom built P. Duncan & Co. Owners Albion Shipping Co.
 Under Dk. 1124 Port belonging to Glasgow Destined Voyage New Zealand.
 If Surveyed Afloat or in Dry Dock Stuggs Key Dock.
(State Name of Dock.)

Years assigned. Character in Register Book.
 Classed 100 A. 1. 7. 81
S.S. Low No. 1. 78.

Last Survey, No. 40623 Port of Low
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Cement When put on 1874
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and re-coated.

This vessel is in good condition and in my opinion eligible to remain as classed.

Committee's Minute Friday, 2nd June, 1882. Chas. Pottoc B.
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at London Date, first Survey 30th May Last Survey 30th May 1882
 No. in on the Siron Ship "Otaki" Master Holbecke
 Reg. Book. 309 Year. Month.
 Tonnage { Net 1014 Built at Newcastle When built 1875
 Gross 1053 By whom built Palmer's Co. Owners N.Z. Shipping Co.
 Under Dk. 885 Port belonging to Littleton, N.Z. Destined Voyage Wellington
 If Surveyed Afloat or in Dry Dock Canal Key Dock
(State Name of Dock.)

Years assigned. Character in Register Book.
 Classed 100 A. 1.
S.S. Low No. 1. 79.
6-8119.

Last Survey, No. 40574 Port of Low
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Cement When put on 1875
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. The Paints brushed.
Bottom cleaned and re-coated.

This vessel is in good condition, and in my opinion eligible to remain as classed.

Committee's Minute Friday, 2nd June, 1882. Chas. Pottoc B.
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 5 for Annual Survey, when there are no repairs. 4000-6, 12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

