

ANNUAL SURVEYS.

41529

No. 205 Survey held at London Date, first Survey May 13th Last Survey May 13th 1882
 No. in on the PS The Lady Carmichael Master H. Munnings
 Reg. Book. 205 Tonnage { Net 124 Built at Dumbarton When built 1871 3
 Gross 369 Under Dk. 368 By whom built A. McMillan Owners Submarine & Telegraph Co.
 Port belonging to London Destined Voyage Dover
 If Surveyed Afloat or in Dry Dock Home & N. by Mr
 (State Name of Dock.)

Last Survey, No. 26489 Port of London

Classed 20 A 4.80
SS Lon M 2.80

Present Condition of the
 Decks Caulked Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cauted When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "

General Observations, Opinion as to Class, &c. Bottom & caulked. Iron shoe put on and put
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Tuesday, 6th June, 1882. Senhouse Martin
 Character assigned 90 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage { Net Built at When built
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON668-0244