

ANNUAL SURVEYS.

41554

No. 553 Survey held at London Date, first Survey May 30th Last Survey May 31st 1882
 No. in on the S Blengfell Master Hall
 Reg. Book. 553 Net 1154 Built at Whitehaven When built 1876 Month. 3
 Tonnage Gross 210 Under Dk. 1125 By whom built Whitehaven S.B. & Co. Owners J. Colebank
 Port belonging to Liverpool Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens by St
(State Name of Dock.)

Last Survey, No. 40609 Port of Liver Classed A 1 7.81
Years assigned. Character in Register Book.

Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails Good
 Wales " Rudder " Anchors, No. of 3 Bw. St & Redg
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now Cables Part on St Good
 Caulking of Bottom, Deck, & Waterways Good Hawsers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c. Bottom be coated. She is now in an efficient state and eligible to remain as classed

Committee's Minute Friday, 9th June, 1882. Senhouse Martindale
 Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 591 Survey held at London Date, first Survey May 22nd Last Survey May 24th 1882
 No. in on the S Loch Awe Master A Nicol
 Reg. Book. 591 Net 1053 Built at Glasgow When built 1869 Month. 4
 Tonnage Gross 1101 Under Dk. 1000 By whom built " Owners J & R Wilson
 Port belonging to Glasgow Destined Voyage Auckland N.Z.
 If Surveyed Afloat or in Dry Dock Bottom Victoria St
(State Name of Dock.)

Last Survey, No. 27612 Port of A Liv Classed A 1 6.81
Years assigned. Character in Register Book.

Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson " Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches " Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Masts, Yards, &c. "
 Planksheers " Keelsons " Condition, how ascertained From St
 Sheerstrakes " Clamps and Shelves " Sails Good
 Topsides " Ceiling " Anchors, No. of 3 Bw. St & Redg
 Wales " Rudder " Cables Part on St Good
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now Hawsers and Warps "
 Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c. Bottom be coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 9th June, 1882. Senhouse Martindale
 Character assigned A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

